
ASSEMBLY INSTRUCTIONS

MIG Torch Rest w/ Cable Hanger & Acc. Plate (Part No. MRM200)


Position and store your MIG torches securely and conveniently for easy access, and to prevent damage to gun and tips.

ReadyRest
Ready when you are.

» Packing List



Cable Hanger can be placed on left or right:



No.	Item	Qty	No.	Item	Qty
1	Adjustable Cable Hanger	1	7	Magnetic Base Mount	1
2	Torch Rest Plate	1	8	Gel Pot	1
3	Rotary Joint Component	1	9	Wing Screw M8 x 16	1
4	Button Head Screw M10 x 16	1	10	U-Clamp	1
5	Washer Ø10	1	11	Button Head Screw M8 x 10	1
6	Standard Accessory Plate	1	12	Washer Ø8	1