
ASSEMBLY INSTRUCTIONS

Table Edge Mount Rest with Cable Hanger (Part No. MRT50)

Position and store your TIG torches securely and conveniently for easy access, and to prevent damage to gun and tips.

ReadyRest
Ready when you are.

» Packing List



No.	Item	Qty
1	Magnetic Base Mount	1
2	Wing Screw M8 x 16	1
3	U-Clamp	1
4	Torch Rest Plate	1
5	Adjustable Cable Hanger	1
6	Washer Ø10	1
7	Wing Screw M10 x 16	1

Cable Hanger can be placed on left or right:

