



ASSEMBLY INSTRUCTIONS

Leg Brace for Welding Tables with 4 Legs

» Packing List



No.	Item	Qty
1	Corner Clamp 1	4
2	Corner Clamp 2	4
3	Hex Nut, M8	16
4	Carriage Bolt, M8	16
5	Circular Tube 1	2
6	Circular Tube 2	2