


ASSEMBLY INSTRUCTIONS

Leg Brace for Welding Tables with 6 Legs

» Packing List



No.	Item	Qty
1	Corner Clamp 1	4
2	Corner Clamp 2	8
3	Hex Nut, M8	28
4	Carriage Bolt, M8	28
5	Line Clamp	2
6	Circular Tube 1	4
7	Circular Tube 2	3