




ASSEMBLY INSTRUCTIONS

Fully articulated Hand Rest(Part No. ARW16)





ReadyRest
Ready when you are.

» Packing List



(3)



No.	Item	Qty	No.	Item	Qty
1	Magnetic Base Mount	1	6	Standpipe	1
2	Balance Plate Assembly	1	7	Fixed Tube Bracket	1
3	Wing Screw M5 x 10	1	8	Pipe Jaw	1
4	Standpipe Base	1	9	Pipe Plug Ø22	2
5	Button Head Screw M10 x 20	1	10	11\"(280mm) Long Rest Bar	1